

## Wellendichtringe

| Bezeichnung                 | Artikelnummer | Bestand |
|-----------------------------|---------------|---------|
| WDR 004*008*02 WA NBR       | 005-0001      | 0       |
| WDR 004*008*02 WAO NBR      | 005-0009      | 0       |
| WDR 004*008*02 WA FPM       | 005-0011      | 0       |
| WDR 004*008*02 WAO FPM      | 005-0019      | 0       |
| WDR 004*012*06 WA NBR       | 005-0175      | 27      |
| WDR 005*015*05 WAS NBR      | 005-0002      | 0       |
| WDR 005*015*05 WC NBR       | 005-0004      | 0       |
| WDR 005*015*05 WAD NBR      | 005-0007      | 0       |
| WDR 005*015*05 WBD NBR      | 005-0008      | 0       |
| WDR 005*015*05 WAS FPM      | 005-0012      | 0       |
| WDR 005*015*05 WC FPM       | 005-0014      | 0       |
| WDR 005*015*05 WCS FPM      | 005-0016      | 0       |
| WDR 005*015*05 WAD FPM      | 005-0017      | 0       |
| WDR 005*015*05 WBD FPM      | 005-0018      | 0       |
| WDR 005*016*06 WB NBR       | 005-0003      | 0       |
| WDR 005*016*06 WB FPM       | 005-0013      | 0       |
| WDR 005*016*06 WA NBR       | 005-0040      | 42      |
| WDR 005*018*07 WA NBR       | 005-0039      | 19      |
| WDR 006*013*04,5 WBO NBR    | 005-0010      | 0       |
| WDR 006*013*04,5 WBO FPM    | 005-0020      | 0       |
| WDR 006*016*07 WA NBR       | 005-0038      | 7       |
| WDR 006*018*05 WA NBR       | 005-0164      | 90      |
| WDR 006*019*06 WA NBR       | 005-0027      | 58      |
| WDR 006*022*07 WA NBR       | 005-0037      | 0       |
| WDR 007,9*016*06,7 WA PTFE  | 005-0234      | 0       |
| WDR 008*016*07 WA NBR       | 005-0160      | 3       |
| WDR 008*016*07 WA FPM       | 005-0225      | 0       |
| WDR 008*022*07 WA NBR       | 005-0026      | 24      |
| WDR 008*022*07 WAS NBR      | 005-0267      | 0       |
| WDR 008*024*07 WA NBR       | 005-0036      | 18      |
| WDR 009*016*04 WA NBR       | 005-0172      | 2       |
| WDR 009*016*05 WA NBR       | 005-0173      | 0       |
| WDR 009*019*05 WCS GE+FE NI | 005-0006      | 0       |
| WDR 009*019*05 WAS NBR      | 005-0021      | 0       |
| WDR 010*016*04 WBO NBR      | 005-0193      | 41      |
| WDR 010*016*04 WA NBR       | 005-0266      | 74      |
| WDR 010*016*04 WA EPDM      | 005-0400      | 0       |
| WDR 010*016*05 WA NBR       | 005-0022      | 76      |

|                            |          |     |
|----------------------------|----------|-----|
| WDR 010*019*05 WBO NBR     | 005-0215 | 0   |
| WDR 010*019*07 WA NBR      | 005-0035 | 11  |
| WDR 010*020*07 WA NBR      | 005-0286 | 30  |
| WDR 010*021*05 WA NBR      | 005-0034 | 30  |
| WDR 010*024*07 AB NBR      | 005-0158 | 0   |
| WDR 010*024*07 WA NBR      | 005-0194 | 10  |
| WDR 010*024*07 WA FPM      | 005-0198 | 29  |
| WDR 010*024*07 WAS FPM     | 005-0269 | 0   |
| WDR 010*024*07 WAS NBR     | 005-0272 | 0   |
| WDR 011*022*07 WA NBR      | 005-0033 | 18  |
| WDR 011*026*07 WA NBR      | 005-0165 | 100 |
| WDR 011,07*023,01*06,3 NBR | 005-0005 | 0   |
| WDR 011,07*023,01*06,3 FPM | 005-0015 | 0   |
| WDR 011,3*017,5*04 WA EPDM | 005-0250 | 0   |
| WDR 012*018*06 WA NBR      | 005-0297 | 0   |
| WDR 012*019*05 WA NBR      | 005-0032 | 17  |
| WDR 012*020*05 WA NBR      | 005-0310 | 10  |
| WDR 012*021*07 WA NBR      | 005-0031 | 20  |
| WDR 012*022*07 WA NBR      | 005-0041 | 1   |
| WDR 012*024*07 WA NBR      | 005-0042 | 12  |
| WDR 012*024*07 WA FPM      | 005-0199 | 40  |
| WDR 012*024*07 WAS NBR     | 005-0273 | 47  |
| WDR 012*025*07 WA NBR      | 005-0251 | 91  |
| WDR 012*025*08 WA NBR      | 005-0241 | 95  |
| WDR 012*027*07 WAS FPM     | 005-0216 | 5   |
| WDR 012*028*07 WA NBR      | 005-0043 | 0   |
| WDR 012*030*07 WA NBR      | 005-0044 | 16  |
| WDR 012*032*07 WA NBR      | 005-0045 | 0   |
| WDR 014*020*05 WA NBR      | 005-0046 | 8   |
| WDR 014*022*05 WAS NBR     | 005-0325 | 0   |
| WDR 014*024*04,5 FPM       | Ko-39542 | 0   |
| WDR 014*028*07 WA NBR      | 005-0047 | 1   |
| WDR 014*028*07 WAS NBR     | 005-0361 | 4   |
| WDR 014*030*07 WA NBR      | 005-0048 | 12  |
| WDR 015*024*07 WA NBR      | 005-0049 | 19  |
| WDR 015*024*07 WAS NBR     | 005-0323 | 3   |
| WDR 015*025*05 WA NBR      | 005-0236 | 92  |
| WDR 015*025*07 WA NBR      | 005-0050 | 0   |
| WDR 015*026*07 WA NBR      | 005-0051 | 13  |
| WDR 015*027*07 WAS FPM     | 005-3006 | 0   |
| WDR 015*030*07 WA NBR      | 005-0052 | 0   |
| WDR 015*032*07 WA NBR      | 005-0053 | 57  |
| WDR 015*032*09 WAS NBR     | 005-0353 | 19  |
| WDR 015*035*07 WA NBR      | 005-0054 | 21  |
| WDR 016*024*05 WA NBR      | 005-0168 | 97  |

|                             |          |     |
|-----------------------------|----------|-----|
| WDR 016*024*07 WA NBR       | 005-0233 | 82  |
| WDR 016*026*07 WA NBR       | 005-0055 | 16  |
| WDR 016*028*07 WA NBR       | 005-0056 | 0   |
| WDR 016*028*07 WA PTFE      | 005-0206 | 0   |
| WDR 016*028*07 WA FPM       | 005-0213 | 0   |
| WDR 016*030*04,5 WA NBR     | 005-0163 | 34  |
| WDR 016*030*07 WA NBR       | 005-0057 | 12  |
| WDR 016*030*07 WA FPM       | 005-0205 | 16  |
| WDR 016*030*10 WA NBR       | 005-0028 | 296 |
| WDR 016*047*07 WA NBR       | 005-0058 | 20  |
| WDR 017*025*04 WAS NBR      | 005-0293 | 44  |
| WDR 017*027*05 WAS NBR      | 005-0308 | 0   |
| WDR 017*028*07 WA NBR       | 005-0059 | 19  |
| WDR 017*030*07 WA NBR       | 005-0060 | 3   |
| WDR 017*032*07 WA NBR       | 005-0061 | 3   |
| WDR 017*035*07 WA NBR       | 005-0062 | 19  |
| WDR 017*040*07 WA NBR       | 005-0063 | 18  |
| WDR 018*025*06 WB NBR       | 005-0204 | 66  |
| WDR 018*028*07 WAS NBR      | 005-0299 | 0   |
| WDR 018*029*07 WAS NBR      | 005-0298 | 0   |
| WDR 018*030*07 WA NBR       | 005-0181 | 4   |
| WDR 018*032*07 WA NBR       | 005-0064 | 18  |
| WDR 018*032*07 WA FPM       | 005-0176 | 11  |
| WDR 018*032*07 WAS NBR      | 005-0263 | 64  |
| WDR 018*032*07 WAS FPM      | 005-0264 | 0   |
| WDR 018*032*07 B2PT         | 005-0290 | 0   |
| WDR 018*032*08 WA NBR       | 005-0245 | 69  |
| WDR 018*034*07 WAS NBR      | 005-3007 | 0   |
| WDR 018*035*07 WA NBR       | 005-0065 | 15  |
| WDR 018*035*10 WA NBR       | 005-0066 | 2   |
| WDR 019*028*07 WA NBR       | 005-0202 | 0   |
| WDR 019*030*07 WA NBR       | 005-0203 | 0   |
| WDR 019*032*08 WAS NBR      | 005-0335 | 3   |
| WDR 019*035*10 WA NBR       | 005-0313 | 9   |
| WDR 019,05*033,33*07,93 NBR | 005-0289 | 5   |
| WDR 020*026*04 WA/oF NBR    | 005-0248 | 2   |
| WDR 020*027*05 WA NBR       | 005-0352 | 2   |
| WDR 020*030*07 WA NBR       | 005-0067 | 19  |
| WDR 020*030*07 WAS NBR      | 005-0283 | 44  |
| WDR 020*030*07 WAS FPM      | 005-0291 | 6   |
| WDR 020*032*07 WA NBR       | 005-0068 | 21  |
| WDR 020*035*07 WA NBR       | 005-0069 | 5   |
| WDR 020*035*07 WA FPM       | 005-0259 | 0   |
| WDR 020*035*07 WAS FPM      | 005-0284 | 5   |
| WDR 020*035*08 WC NBR       | 005-0070 | 18  |

|                          |          |    |
|--------------------------|----------|----|
| WDR 020*042*07 WA NBR    | 005-0191 | 41 |
| WDR 020*042*10 WA NBR    | 005-0071 | 1  |
| WDR 020*047*07 WA NBR    | 005-0072 | 40 |
| WDR 020*047*08 WA NBR    | 005-1444 | 3  |
| WDR 020*047*10 WA NBR    | 005-0073 | 0  |
| WDR 020*052*07 WA NBR    | 005-0074 | 70 |
| WDR 021*032*07 WAS NBR   | 005-0334 | 18 |
| WDR 021*033*07 WAS NBR   | 005-0318 | 0  |
| WDR 022*032*05,5 FPM     | Ko-37358 | 0  |
| WDR 022*032*07 WA NBR    | 005-0075 | 48 |
| WDR 022*032*07 WA PTFE   | 005-0222 | 0  |
| WDR 022*032*07 WAS FPM   | 005-0243 | 17 |
| WDR 022*035*07 WA NBR    | 005-0268 | 38 |
| WDR 022*035*07 WAS FPM   | 005-0360 | 4  |
| WDR 022*040*07 WA NBR    | 005-0195 | 49 |
| WDR 022*040*07 WA FPM    | 005-0200 | 0  |
| WDR 022*040*07 WAS FPM   | 005-0261 | 0  |
| WDR 022*040*07 WAS NBR   | 005-0262 | 55 |
| WDR 022*040*10 WA NBR    | 005-0179 | 1  |
| WDR 022*042*07 WA NBR    | 005-0214 | 0  |
| WDR 022*047*07 WA FPM    | 005-0212 | 0  |
| WDR 023*037*07 WA NBR    | 005-0076 | 0  |
| WDR 024*036*07 WAS NBR   | 005-0301 | 7  |
| WDR 024*047*10WA NBR     | 005-0166 | 54 |
| WDR 025*032*04WAS FPM    | 005-0358 | 0  |
| WDR 025*032*06WA NBR     | 005-0246 | 36 |
| WDR 025*035*06 WA FPM    | 005-0024 | 0  |
| WDR 025*035*07 WAS NBR   | 005-0167 | 23 |
| WDR 025*035*07 WA NBR    | 005-0255 | 37 |
| WDR 025*036*06 WAS NBR   | 005-3013 | 0  |
| WDR 025*036*07 WA FPM    | 005-0336 | 0  |
| WDR 025*040*07 WA NBR    | 005-0196 | 5  |
| WDR 025*040*07 WA FPM    | 005-0201 | 0  |
| WDR 025*040*07 WA PTFE   | 005-0230 | 0  |
| WDR 025*040*07 WAS NBR   | 005-0363 | 0  |
| WDR 025*040*08 WAS NBR   | 005-1006 | 11 |
| WDR 025*040*10 WA NBR    | 005-0077 | 1  |
| WDR 025*040*10 WAS NBR   | 005-3012 | 9  |
| WDR 025*042*07 WA NBR    | 005-0254 | 5  |
| WDR 025*042*08 WA NBR    | 005-0331 | 50 |
| WDR 025*047*07 WA NBR    | 005-0078 | 3  |
| WDR 025*062*10 WA NBR    | 005-0260 | 15 |
| WDR 026*042*07 WA NBR    | 005-0079 | 17 |
| WDR 027*034*03 NBR Blech | 005-3009 | 0  |
| WDR 027*034*03 NBR Blech | 005-3010 | 0  |

|                               |          |    |
|-------------------------------|----------|----|
| WDR 028*035*04 NBR Blech      | 005-3011 | 2  |
| WDR 028*040*07 WA NBR         | 005-0080 | 0  |
| WDR 028*040*07 WA FPM         | 005-0197 | 0  |
| WDR 028*042*08 WA NBR         | 005-0332 | 36 |
| WDR 028*042*08 WAS NBR        | 005-3015 | 2  |
| WDR 028*043*08 WAS NBR        | 005-3017 | 0  |
| WDR 028*047*07 WA NBR         | 005-0081 | 0  |
| WDR 028*050*10 WA NBR         | 005-0242 | 16 |
| WDR 028*052*10 WA NBR         | 005-0082 | 11 |
| WDR 028*052*10 WAS NBR        | 005-0231 | 20 |
| WDR 029*047*07 WA NBR         | 005-0083 | 0  |
| WDR 029*050*10 WA NBR         | 005-0319 | 7  |
| WDR 030*040*07 WA NBR         | 005-0084 | 38 |
| WDR 030*040*07 WA PTFE        | 005-0223 | 0  |
| WDR 030*040*07 WAS FPM        | 005-0294 | 3  |
| WDR 030*042*07 WA NBR         | 005-0085 | 31 |
| WDR 030*042*08 WAS NBR        | 005-3014 | 2  |
| WDR 030*043*07 WA NBR         | 005-0276 | 0  |
| WDR 030*043*08 WAS NBR        | 005-3016 | 0  |
| WDR 030*045*08 WAS FPM        | 005-0295 | 0  |
| WDR 030*047*07 WA NBR         | 005-0086 | 10 |
| WDR 030*050*07 WAS FPM        | 005-0333 | 0  |
| WDR 030*050*10 WAS NBR        | 005-0282 | 14 |
| WDR 030*052*07 WA NBR         | 005-0087 | 18 |
| WDR 030*052*07 WAS NBR        | 005-0305 | 0  |
| WDR 030*052*10 WAS NBR        | 005-0088 | 30 |
| WDR 030*052*10 WAS NBR        | 005-0270 | 0  |
| WDR 030*052*12 WA NBR         | 005-0025 | 0  |
| WDR 030*062*07 WA NBR         | 005-0089 | 19 |
| WDR 030*072*10 WA NBR         | 005-0090 | 19 |
| WDR 032*042*07 WA NBR         | 005-0091 | 16 |
| WDR 032*045*07 WA NBR         | 005-0092 | 44 |
| WDR 032*045*07 WA FPM         | 005-0207 | 2  |
| WDR 032*047*07 WA NBR         | 005-0093 | 2  |
| WDR 032*050*07 WA NBR         | 005-0094 | 9  |
| WDR 032*052*07 WA NBR         | 005-0095 | 4  |
| WDR 032*052*10 WA NBR         | 005-0287 | 5  |
| WDR 034*050*07 WAS NBR        | 005-0265 | 37 |
| WDR 034,92*050,8*07,93 WA NBR | 005-0303 | 19 |
| WDR 035*047*06/6,5 BABSL FPM  | 005-1007 | 0  |
| WDR 035*047*07 WA FPM         | 005-0029 | 0  |
| WDR 035*047*07 WA NBR         | 005-0096 | 0  |
| WDR 035*047*07 WB NBR         | 005-0170 | 15 |
| WDR 035*047*07 WC NBR         | 005-0187 | 0  |
| WDR 035*047*07 WAS NBR        | 005-0217 | 1  |

|                         |          |    |
|-------------------------|----------|----|
| WDR 035*052*05 WAS NBR  | 005-0356 | 0  |
| WDR 035*052*07 WA NBR   | 005-0097 | 0  |
| WDR 035*055*09 WAS NBR  | 005-0315 | 6  |
| WDR 035*062*10 WA NBR   | 005-0098 | 8  |
| WDR 035*062*12 WA NBR   | 005-0224 | 27 |
| WDR 035*072*12WA NBR    | 005-0099 | 10 |
| WDR 036*047*07 WA NBR   | 005-3005 | 6  |
| WDR 036*058*12 WAS NBR  | 005-0355 | 0  |
| WDR 036*062*07 WA NBR   | 005-0100 | 1  |
| WDR 038*050*07 WA NBR   | 005-0101 | 4  |
| WDR 038*052*07 WA NBR   | 005-0102 | 55 |
| WDR 038*052*07 WA FPM   | 005-0275 | 0  |
| WDR 038*052*07 WAS FPM  | 005-0285 | 2  |
| WDR 038*058*11 WAS NBR  | 005-0354 | 4  |
| WDR 039*051*07,5 WA NBR | 005-0161 | 3  |
| WDR 040*047*04 WAS NBR  | 005-1001 | 0  |
| WDR 040*050*06 B NBR    | 005-0357 | 0  |
| WDR 040*052*05 WA NBR   | 005-0253 | 17 |
| WDR 040*052*06 WA NBR   | 005-0220 | 49 |
| WDR 040*052*07 WA NBR   | 005-0103 | 42 |
| WDR 040*055*07 WA NBR   | 005-0252 | 19 |
| WDR 040*056*07 WAS NBR  | 005-0304 | 4  |
| WDR 040*058*08 WAS FPM  | 005-0350 | 1  |
| WDR 040*060*10 WA NBR   | 005-0104 | 5  |
| WDR 040*062*06 WA NBR   | 005-3018 | 0  |
| WDR 040*062*07 WA NBR   | 005-0105 | 8  |
| WDR 040*062*10 WA NBR   | 005-0226 | 24 |
| WDR 040*062*10 WAS NBR  | 005-0271 | 17 |
| WDR 040*062*10 WAS FPM  | 005-0306 | 0  |
| WDR 040*065*10 WA NBR   | 005-0106 | 2  |
| WDR 040*072*07 WA NBR   | 005-0107 | 2  |
| WDR 040*072*10 WA NBR   | 005-0108 | 9  |
| WDR 040*080*10 WA NBR   | 005-0109 | 10 |
| WDR 040*090*12 WA NBR   | 005-0110 | 10 |
| WDR 042*055*08 WA NBR   | 005-0111 | 9  |
| WDR 042*056*07 WA NBR   | 005-0205 | 41 |
| WDR 042*062*07 WC NBR   | 005-0209 | 15 |
| WDR 042*062*08 WA NBR   | 005-0221 | 33 |
| WDR 042*065*10 WA NBR   | 005-0112 | 3  |
| WDR 042*072*12 WA NBR   | 005-0113 | 0  |
| WDR 042*072*12 WC NBR   | 005-0171 | 1  |
| WDR 045*055*07 WA NBR   | 005-0114 | 10 |
| WDR 045*055*07 WAS NBR  | 005-0362 | 0  |
| WDR 045*060*07 WA NBR   | 005-0030 | 0  |
| WDR 045*060*07 WAS FPM  | 005-0208 | 0  |

|                              |          |    |
|------------------------------|----------|----|
| WDR 045*062*07 ASH/BABSL NBR | 005-0345 | 0  |
| WDR 045*062*08 WB NBR        | 005-0116 | 2  |
| WDR 045*062*10 WC NBR        | 005-0117 | 3  |
| WDR 045*062*10 WC NBR        | 005-0237 | 0  |
| WDR 045*062*10 WAS NBR       | 005-0244 | 0  |
| WDR 045*062*10 WA NBR        | 005-0258 | 30 |
| WDR 045*065*08 WA NBR        | 005-0118 | 2  |
| WDR 045*065*10 WA NBR        | 005-0119 | 5  |
| WDR 045*068*09 WAS NBR       | 005-0316 | 6  |
| WDR 045*068*10 WAS NBR       | 005-0329 | 3  |
| WDR 045*072*08 WA NBR        | 005-0120 | 2  |
| WDR 045*072*10 WAS FPM       | 005-0349 | 1  |
| WDR 045*075*07 WA NBR        | 005-0121 | 52 |
| WDR 045*080*10 WA NBR        | 005-0122 | 16 |
| WDR 045*080*10 WAS NBR       | 005-0232 | 15 |
| WDR 048*062*07 WAS NBR       | 005-0359 | 5  |
| WDR 048*062*08 WA NBR        | 005-0123 | 8  |
| WDR 048*068*10 WAS NBR       | 005-0330 | 3  |
| WDR 050*062*10 WA NBR        | 005-0211 | 27 |
| WDR 050*065*08 WA NBR        | 005-0124 | 24 |
| WDR 050*065*08 WA FPM        | 005-0347 | 0  |
| WDR 050*065*10 WA NBR        | 005-0249 | 30 |
| WDR 050*065*10 WA FPM        | 005-0348 | 0  |
| WDR 050*068*08 WA NBR        | 005-0125 | 3  |
| WDR 050*070*10 WA NBR        | 005-0126 | 27 |
| WDR 050*072*09 WAS NBR       | 005-0317 | 10 |
| WDR 050*072*10 WA NBR        | 005-0127 | 4  |
| WDR 050*072*10 WC NBR        | 005-0182 | 1  |
| WDR 050*072*12 WAS NBR       | 005-0302 | 9  |
| WDR 050*080*08 WA NBR        | 005-0128 | 9  |
| WDR 050*080*10 WA NBR        | 005-0129 | 11 |
| WDR 052*068*08 WAS NBR       | 005-0320 | 2  |
| WDR 052*072*10 WAS NBR       | 005-0247 | 2  |
| WDR 052*072*12 WAS NBR       | 005-0300 | 0  |
| WDR 055*068*08 WA NBR        | 005-0235 | 29 |
| WDR 055*070*08 WA NBR        | 005-0240 | 13 |
| WDR 055*070*08 WA FPM        | 005-0321 | 0  |
| WDR 055*072*10 WA NBR        | 005-0130 | 0  |
| WDR 055*100*10 WA NBR        | 005-0131 | 8  |
| WDR 056*070*08 WA NBR        | 005-0177 | 24 |
| WDR 056*072*08 WA NBR        | 005-0132 | 3  |
| WDR 056*080*12 WAS FPM       | 005-0278 | 8  |
| WDR 058*072*08 WA NBR        | 005-0133 | 34 |
| WDR 058*080*10 WAS FPM       | 005-0279 | 7  |
| WDR 060*075*08 WA NBR        | 005-0134 | 2  |

|                             |          |    |
|-----------------------------|----------|----|
| WDR 060*075*08 WC NBR       | 005-0351 | 0  |
| WDR 060*075*10 WA NBR       | 005-0136 | 0  |
| WDR 060*080*08 WA NBR       | 005-0135 | 0  |
| WDR 060*080*10 WAS NBR      | 005-0218 | 0  |
| WDR 060*080*13 WAS NBR      | 005-0277 | 17 |
| WDR 060*082*12 WAS NBR      | 005-0312 | 0  |
| WDR 060*085*08 WA NBR       | 005-0137 | 0  |
| WDR 060*085*13 WAS NBR      | 005-0280 | 9  |
| WDR 060*090*10 WA NBR       | 005-0138 | 10 |
| WDR 060*090*10 WC NBR       | 005-0183 | 3  |
| WDR 060*090*13 WA NBR       | 005-0139 | 0  |
| WDR 060*090*13 WC NBR       | 005-0184 | 1  |
| WDR 062*085*10 WA NBR       | 005-0141 | 2  |
| WDR 065*080*08 WAS FPM      | 005-0292 | 0  |
| WDR 065*085*13 WA NBR       | 005-0142 | 0  |
| WDR 065*085*13 WC NBR       | 005-0185 | 2  |
| WDR 065*090*10 WA NBR       | 005-0143 | 0  |
| WDR 065*090*10 WC NBR       | 005-0238 | 0  |
| WDR 065*100*10 WA NBR       | 005-0140 | 2  |
| WDR 068*090*10 WA NBR       | 005-0144 | 1  |
| WDR 068*090*12 WC NBR       | 005-0180 | 0  |
| WDR 070*085*08 WAS NBR      | 005-0169 | 4  |
| WDR 070*085*08 WBS Perb.    | 005-0174 | 0  |
| WDR 070*090*10 WA NBR       | 005-0145 | 45 |
| WDR 070*090*13 WA NBR       | 005-0146 | 0  |
| WDR 070*090*13 WC NBR       | 005-0186 | 3  |
| WDR 070*100*13 WA NBR       | 005-0147 | 3  |
| WDR 070*100*13 WC NBR       | 005-0159 | 7  |
| WDR 075*090*10 WAS NBR      | 005-0311 | 3  |
| WDR 075*095*10 WA NBR       | 005-0148 | 4  |
| WDR 075*100*10 WA NBR       | 005-0149 | 1  |
| WDR 075*100*12BAFU DSL*7NBR | 005-0257 | 0  |
| WDR 075*100*13 WA NBR       | 005-0150 | 0  |
| WDR 075*100*13 WC NBR       | 005-0190 | 8  |
| WDR 078*100*10 WA NBR       | 005-0151 | 1  |
| WDR 080*100*13 WA NBR       | 005-0152 | 2  |
| WDR 080*100*13 WC NBR       | 005-1115 | 0  |
| WDR 080*110*10 WA NBR       | 005-0153 | 0  |
| WDR 080*120*13 WC NBR       | 005-0115 | 2  |
| WDR 080*120*13 WA NBR       | 005-0154 | 0  |
| WDR 085*100*9 Metall Aussen | 005-0296 | 0  |
| WDR 085*105*10 WAS FPM      | 005-0307 | 0  |
| WDR 090*110*12 WA NBR       | 005-0155 | 1  |
| WDR 090*110*8 WA NBR        | 005-3008 | 0  |
| WDR 090*120*12 WA NBR       | 005-0156 | 3  |

|                          |          |    |
|--------------------------|----------|----|
| WDR 095*125*13 WA NBR    | 005-0157 | 0  |
| WDR 095*125*13 WC NBR    | 005-0192 | 3  |
| WDR 100*120*12 WA NBR    | 005-0322 | 0  |
| WDR 100*120*13 WC NBR    | 005-0162 | 52 |
| WDR 105*130*13 B2 NBR    | 005-1002 | 0  |
| WDR 110*150*13 WA NBR    | 005-0023 | 0  |
| WDR 120*140*13 WCS Perb. | 005-0189 | 0  |
| WDR 120*160*15 B2 NBR    | 005-0999 | 1  |
| WDR 125*160*15 B2 NBR    | 005-0998 | 0  |
| WDR 138*160*15 B2 NBR    | 005-0178 | 0  |
| WDR 140*170*12 WAS NBR   | 005-0346 | 0  |
| WDR 145*160*10 WA NBR    | 005-0219 | 0  |
| WDR 150*170*15 B2 NBR    | 005-0281 | 0  |
| WDR 150*170*15 B2 PTFE   | 005-0309 | 0  |
| WDR 160*190*15 C FPM     | 005-1000 | 0  |
| WDR 310*285*16 B2SL NBR  | 005-0314 | 0  |
| WDR 620*680*25 WCL Perb. | 005-0210 | 0  |